

## NEW 1 Pole 10kA Miniature Circuit Breakers



Part No.	Description	Box Qty
CB106B	1Pole 6Amps B Curve 10kA MCB	12
CB110B	1Pole 10Amps B Curve 10kA MCB	12
CB116B	1Pole 16Amps B Curve 10kA MCB	12
CB120B	1Pole 20Amps B Curve 10kA MCB	12
CB132B	1Pole 32Amps B Curve 10kA MCB	12
CB140B	1Pole 40Amps B Curve 10kA MCB	12
CB150B	1Pole 50Amps B Curve 10kA MCB	12
CB363C	1Pole 63Amps B Curve 10kA MCB	12
CB106C	1Pole 6Amps C Curve 10kA MCB	12
CB110C	1Pole 10Amps C Curve 10kA MCB	12
CB116C	1Pole 16Amps C Curve 10kA MCB	12
CB120C	1Pole 20Amps C Curve 10kA MCB	12
CB132C	1Pole 32Amps C Curve 10kA MCB	12
CB140C	1Pole 40Amps C Curve 10kA MCB	12
CB150C	1Pole 50Amps C Curve 10kA MCB	12
CB163C	1Pole 63Amps C Curve 10kA MCB	12
CB106D	1Pole 6Amps D Curve 10kA MCB	12
CB110D	1Pole 10Amps D Curve 10kA MCB	12
CB116D	1Pole 16Amps D Curve 10kA MCB	12
CB120D	1Pole 20Amps D Curve 10kA MCB	12
CB132D	1Pole 32Amps D Curve 10kA MCB	12
CB140D	1Pole 40Amps D Curve 10kA MCB	12
CB150D	1Pole 50Amps D Curve 10kA MCB	12
CB163D	1Pole 63Amps D Curve 10kA MCB	12

## NEW 2 Pole 10kA Miniature Circuit Breakers



Part No.	Description	Box Qty
CB206B	2Pole 6Amps B Curve 10KA	6
CB210B	2Pole 10Amps B Curve 10KA	6
CB216B	2Pole 16Amps B Curve 10KA	6
CB220B	2Pole 20Amps B Curve 10KA	6
CB232B	2Pole 32Amps B Curve 10KA	6
CB240B	2Pole 40Amps B Curve 10KA	6
CB250B	2Pole 50Amps B Curve 10KA	6
CB263B	2Pole 63Amps B Curve 10KA	6
CB206C	2Pole 6Amps C Curve 10KA	6
CB210C	2Pole 10Amps C Curve 10KA	6
CB216C	2Pole 16Amps C Curve 10KA	6
CB220C	2Pole 20Amps C Curve 10KA	6
CB232C	2Pole 32Amps C Curve 10KA	6
CB240C	2Pole 40Amps C Curve 10KA	6
CB250C	2Pole 50Amps C Curve 10KA	6
CB263C	2Pole 63Amps C Curve 10KA	6